

5/11

Switching Sequence of A, A', B, B', C, C' for Figure 2A

1 Close A, A', C, C' (reset Cs1, Cs2)

2 Float all switches

3 Close B, B' (charge Cs1, Cs2)

4 Float all switches

5 Close A, A' (clamp strip to ground)

6 Measure 1, 2

7 goto step 1 if desired

Fig. 3a

Switching Sequence of A, A', B, B', C, C' for Figure 2B

1 Reset Counters CT1, CT2

2 Close A, A', C, C' (reset Cs1, Cs2)

3 Float all switches

4 Close B, B' (Charge Cs1, Cs2)

5 Float all switches

6 Close A, A' (Clamp strip to ground)


7 if (VCs1 < Vt) then increment CT1; if (VCs2 < Vt) then increment CT2

8 If ((VCs1 < Vt) OR (VCs2 < Vt)) then goto step 3


9 Float all switches


10 goto step 1 to repeat (if desired)


Fig. 3b





F16.4














Fig 12

